

Installation of the Renovatio SRD-R3 Mount for Thrustmaster TS-PC, T300 & TX Servo Base

This guide will take you step by step through the installation of your new digital display mounting bracket.

CAUTION: Be careful to avoid static build-up while handling the electronics On your wheel. Ricmotech is not responsible for any damage you may cause to your wheel.



Mount the SRD-R3 to the bracket using the supplied screws into the back of the R3.



Remove the “nose” cover by first removing the quick-release security screw then removing the four screws securing the nose.

Plug the supplied cable into the back of the SRD-R3 and route the cable around the outside of the screw bosses as shown below to keep the cable away from moving parts.



Place the bracket over the front of the servo base and mount using the original screws and the washers supplied.

Be sure to route the cable out the bottom utilizing the groove on the back side.



Mount your wheel and replace the security screw on the quick release.

Proceed to download and install the SRD-M3 software and then plug the USB cable into your PC.

Need Help?

If you run into any problems during the installation, please contact us directly at technical support at (305) 417-9241 or via email at mail@ricmotech.com.

Due to constant improvements to our products, the product you receive may vary slightly from the product shown in the illustrations.

Copyright 2017, Ricmotech LLC

Thrustmaster® is a trademark of the Guillemot® company and the terms are used for reference purposes only. Ricmotech LLC is not affiliated with Thrustmaster®.

Renovatio Development and the terms are used for reference purposes only. Ricmotech LLC is not affiliated with Renovatio Development.